

3) MOTORS

COVERING

COVER FUSELAGE & WINGS WITH SILK & GIVE 4 COATS OF CLEAR DOPE. COVER TAIL SURFACES WITH HEAVY MODELSPAN & GIVE 2 COATS OF CLEAR DOPE. FINISH WITH COLOUR DOPE TO SELECTED SCHEME.

END FACINGS 4 OFF TO DOTTED LI
(FIT AFTER BUILDING WINGS)

SLAT

WING RIBS

TUBE SLOTS IN $\frac{1}{8}$ " SHEET RIBS ONLY

